




Wymiary prowadnic



| | | | | | | | | | | | | | | | |
|------------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|------|------|------|
| A | 400 | 450 | 500 | 550 | 600 | 650 | 700 | 750 | 800 | 850 | 900 | 950 | 1000 | 1100 | 1200 |
| B±3 | 400 | 450 | 500 | 550 | 600 | 650 | 700 | 750 | 800 | 850 | 900 | 950 | 1000 | 1100 | 1200 |

Mocowanie prowadnic do korpusu



Mocowanie prowadnic do szuflady

| L | A | B | C | D | E | F |
|-------------|-----|-----|------|-----|-----|------|
| 400 | 128 | 288 | - | 96 | 288 | - |
| 450 | 160 | 320 | - | 128 | 320 | - |
| 500 | 192 | 384 | - | 160 | 384 | - |
| 550 | 192 | 416 | - | 192 | 416 | - |
| 600 | 128 | 288 | 480 | 192 | 352 | 480 |
| 650 | 160 | 320 | 512 | 192 | 384 | 544 |
| 700 | 192 | 384 | 576 | 192 | 384 | 576 |
| 750 | 192 | 384 | 576 | 192 | 416 | 608 |
| 800 | 224 | 448 | 672 | 224 | 448 | 672 |
| 850 | 224 | 448 | 672 | 224 | 448 | 672 |
| 900 | 256 | 512 | 768 | 256 | 512 | 768 |
| 950 | 256 | 544 | 832 | 256 | 544 | 832 |
| 1000 | 288 | 576 | 864 | 288 | 576 | 864 |
| 1100 | 288 | 608 | 928 | 288 | 608 | 928 |
| 1200 | 352 | 704 | 1056 | 320 | 672 | 1024 |